

April 2, 2021

### **Public Notice**

On the morning of April 1, 2021, a sewer force main at a lift station (sewage pumping station) at 1114 1<sup>st</sup> Avenue East, Menomonie, Wisconsin, was found to be cracked and leaking. A small amount of water was seeping up through the soil but only when the pump was running. The pump was immediately shut off and the Wisconsin Department of Natural Resources was notified.

This lift station only serves three homes so the volume of water was small. The water appeared to be seeping back into the soil and is not believed to have entered any surface waters. The lift station is being pumped by truck and hauled to the wastewater treatment plant until repairs can be made.

Pursuant to the requirement of NR 210 of the Wisconsin Administrative Code, this public notice is being posted regarding this event.